

Truss Bridges on the MoDOT System that do NOT Need Their Gusset Plates Checked

Dist	County	Bridge No.	Facility Carried	Feature Intersected	Year Built	ADT
07	BARRY	A0260	MO 39 S	TABLE ROCK LK	1958	3,988
07	BARRY	J0382	MO 248 E	FLAT CR	1930	1,194
07	BARTON	N0192	RT T S	PETTIS CR	1956	756
07	BATES	G0864	MO 52 E	MIAMI CR	1924	1,776
07	BATES	R0115	RT V S	MARAIS DES CYGNES	1961	370
07	BATES	T0280	RT B E	MARAIS DES CYGNES	1934	1,018
07	CEDAR	H0622	MO 32 E	HORSE CR	1927	1,309
07	CEDAR	H0623	MO 32 E	CEDAR CR	1930	1,688
07	CEDAR	N0504	RT CC E	HORSE CR	1958	238
07	CEDAR	S0979	MO 97 S	HORSE CR	1954	616
07	CEDAR	X0190	MO 39 S	CEDAR CR	1949	530
07	JASPER	T0373	RT H E	N FK SPRING RVR	1933	680
07	JASPER	T0425	RT D E	CENTER CR	1935	4,610
07	JASPER	T0426	RT O S	SPRING RVR	1935	846
07	JASPER	X0435	RT M E	N FK SPRING RVR	1949	562
07	JASPER	Y0593	RT D E	SPRING RVR	1900	3,120
07	LAWRENCE	H0787	BU 60 E	BNSF RR	1935	1,546
07	LAWRENCE	P0701	RT DD E	TURNBACK CR	1955	378
07	MCDONALD	H0792	RT EE E	INDIAN CR	1928	992
07	VERNON	X0186	RT B E	HORSE CR	1947	733

